

ವಿಭಾಗೀಯ ಕಛೇರಿ,
ಕರ್ನಾಟಕ ರಾಜ್ಯ ಮಾಲಿನ್ಯ ನಿಯಂತ್ರಣ ಮಂಡಳಿ,
ಸಿ.ಎ-2, 3ನೇ ಹಂತ,
ಕೆ.ಎಚ್.ಬಿ. ಕಾಲೋನಿ, ಪ್ರಗತಿ ಗ್ರಾಮೀಣ ಬ್ಯಾಂಕ್ ಹಿಂಭಾಗ,
ಕೆ.ಎಚ್.ಬಿ. ಕಛೇರಿ ಹತ್ತಿರ, ಸಾಡಿಕ ನಗರ ರಸ್ತೆ,
ಚಿತ್ರದುರ್ಗ-577501



Divisional Office,
Karnataka State Pollution Control Board,
C.A-2, 3rd Main,
KHB Colony, Behind Pragathi Gramin Bank,
Near KHB Office, Sadik Nagar Road,
Chitradurga-577501

No.PCB/SEO-CTA/Random Inspection/2017/ 264

October 17, 2017

Inspection Notes of C.D.Kumar, SEO, Chitradurga

Name of The Industry visited	M/s. Elite India Construction Pvt Ltd, Unit -II The Biere Street, Sy.No.153/1, Hagadur Village KR Puram Hobli, Bengaluru 560066
Date of Visit	06.10.2017
Officers Accompanied	Dr. Puttaraju, DEO, RO-Mahadevapura
Person Contacted	Vijay, Unit Manager

It is a Microbrewery unit engaged in brewing of variety of beer for which the Board has issued consent under Water Act 1974 & Air Act 1981 for the period up to 30.09.2021 with conditions. The unit was visited in view of the instructions issued through e-mail dated 04.09.2017 under random inspection of organization identified based on computerized risk assessment. The unit was in operation during visit and following are the observations.

- The Board has granted consents for brewing beer 15208 KLT per month and to a query the Manager informed that presently they are brewing 7000-8000 lts of 6 types of beer per month and serving in two restaurants (about 120 seating capacity total) existing within the brewery premises. On verification of brewing data the unit has produced 7367 lts of beer during September 2017. Copy of the production & sale details is enclosed.
- The unit is having one electrically heated hot water tank and two DG sets of 125 KVA. For DG Sets individual chimneys of 7 Mts AGL are provided. Another old DG Set of 62.5 KVA has been dismantled.
- The unit has provided common treatment system for the treatment of sewage generated from restaurants and small quantity of trade effluents from brewing unit. The treatment system was in partial operation during visit. Oil & grease removal and sludge removal is not effective and as result foul smell noticed near treatment unit. The Manger was instructed to revamp the treatment units immediately for effective function including removal of sludge deposited for long period. Adequate land is available for utilization of treated effluents and the unit needs to improve greenery in parking area.
- To a query about the spent grain generated as solid waste in brewery the Manager informed that presently about 150 Kgs/week is generated and the same is is being disposed to farmers as cattle feed. He was instructed to maintain record in this regard with full details. Besides the unit generates both organic & inorganic solid wastes from restaurants (about 50-100kgs/day) said to be given to contractor on daily basis. In this regard the Manager was instructed to secure mode of disposal from the contractor and to maintain detailed record.

Based on the observations notice may be issued for non-compliances, besides the consent conditions could be reviewed for discharge standards and air pollution sources. The photographs taken during visit are enclosed.

Encl. as above


SEO-Chitradurga